



# SkyPanel

**Firmware Version: 4.1**

KNOWN ISSUE REPORT

## Know Issues: FW Version: 4.1.0

Issue	Consequence	Estimated Completion Date
S30-RP Startup Fault	The fixture startup of a S30-RP might result in a PSU fault. This can be resolved by changing the intensity to 0% and then back to any desired intensity value.	1 <sup>st</sup> Half 2019

**ALSM:** (ARRI Lighting Software Manager) PC application for updating firmware and setting attributes of ARRI LED fixtures.

**DMX:** Communication protocol designed for lighting fixtures in the film, TV and live entertainment markets

**RDM:** (Remote Device Management) Two-way communication protocol designed to read and set attributes of a light fixture

### NOTES:

- If using a USB flash drive to update your SkyPanel, please use a USB drive that is USB 1.0 or 2.0 and is formatted to FAT or FAT32. The update file must be in the root directory of the drive and the USB Mode on the SkyPanel must be set to "Normal".
- Do not downgrade SkyPanel S360-C to a version lower than 3.2 – doing so may result in fixture malfunction.
- Read all warnings and notices in the SkyPanel User Manual.