# SkyPanel
# Firmware Version: 4.3

Date: 5-May-22

## Know Issues: FW Version: 4.3.0

| Issue | Consequence | Estimated Completion Date |
|---|---|---|
| Multi ArtNet Controllers risk | If receiving ArtDMX from more than two ArtNet Controllers via Ethernet, S30, S60 or S120 might reboot. | Next Update |

**ALSM:** (ARRI Lighting Software Manager) PC application for updating firmware and setting attributes of ARRI LED fixtures.

**DMX:** Communication protocol designed for lighting fixtures in the film, TV and live entertainment markets

**RDM:** (Remote Device Management) Two-way communication protocol designed to read and set attributes of a light fixture

**NOTES:**
- If using a USB flash drive to update your SkyPanel, please use a USB drive that is USB 1.0 or 2.0 and is formatted to FAT or FAT32. The update file must be in the root directory of the drive and the USB Mode on the SkyPanel must be set to "Normal".
- Do not downgrade SkyPanel S360-C to a version lower than 3.2 – doing so may result in fixture malfunction.
- Read all warnings and notices in the SkyPanel User Manual.